## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patentee:

Shea Chen, et al.

U.S. Patent No.:

US 6,803,534 B1

Issued:

October 12, 2004

Serial No.:

09/866,205

Filed:

May 25, 2001

Group No.:

2833

Examiner:

Renee Luebke

Confirmation No.:

4344

Title:

MEMBRANE FOR MICRO-ELECTRO-MECHANICAL SWITCH, AND METHODS OF MAKING AND USING IT

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Dear Sir:

## REQUEST FOR CERTIFICATE OF CORRECTION UNDER 37 CFR § 1.322

It is respectfully requested that a Certificate of Correction be issued in accordance with the enclosed Form PTO-1050. The error involved is believed to be a Patent Office error, and it is believed that no fee is due in association with this request for a Certificate of Correction. However, the Commissioner is hereby authorized to charge any fees or credit any overpayments to Deposit Account No. 02-0384 of Baker Botts L.L.P.

It is respectfully submitted that a significant error is present in the printed patent, that correction thereof in accordance with the enclosed Form PTO-1050 is required in order that no misunderstanding will occur.

Respectfully submitted,

Attorneys for Applicants

g. No. 40 227

Date: 1/17/0

Customer No. 45507